

Index File No.	CORNER RECORD (SEARCH)		Tract or Survey No.	Cor. No. <u>V-7</u>
T <u>3S</u> R. <u>8W</u>	R.D. <u>HeBo</u>	County <u>TILLAMOOK</u>	# <u>478</u>	
Merid. <u>Will.</u>	N.F. <u>Sius</u>	State <u>ORE</u>		
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND			
	<u>POST GONE</u>			
PHOTO IDENTIFICATION DATA	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND			
Photo No. _____ Filed At. _____ Object Ident. _____ Ident. By _____ <i>Signature</i>	FOUND <u>54" FIR, S. 75° W., 41 1/2 FT. WITH HEALED WITNESS FACE. (ORIG)</u> THE ORIG. BT IN SEC. 29 IS GONE. FOUND A <u>38" SNAG, N. 34° E., 159 FT. MARKED 1/4 S</u> OF WHICH			
PLANE COORDINATE POSITION DATA	DESCRIBE CORNER LOCATION RELATIVE TO NEAR BY FEATURES, ALSO HOW TO REACH CORNER			
State _____ Zone _____ X _____ Y _____ Estab. By _____ <i>Agency</i>	THERE IS NO RECORD IN THE ORIG. NOTES. THE MARKS APPEAR TO HAVE BEEN MADE BY A POCKET - KNIFE PERHAPS 50 OR 60 YEARS AGO.			
Signature <u>Leonard Whitmore</u>	Title <u>Forestry Tech</u>	Division <u>Timber</u>	Headquarters <u>Hebo</u>	Date <u>3-6-65</u> 5680-2 REV. '65 5

CORNER RECORD (PERPETUATION)	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE	RESERVE EXISTING MONUMENT
<u>SET "3" X "3" POST 24" ABOVE GROUND.</u>	
ACCESSORIES: DESCRIBE NEW BT & WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE	
<u>NEW BT</u> <u>16" FIR, N. 7° E., 19 FT. MARKED 1/4 S 29 BT.</u>	
Work Done By _____	Title _____ Date _____ State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes No	Filed At: _____ Date _____
REMARKS	
<u>WITNESS: DARYL WHITMORE MERVIN WHITMORE WAS A M. WHITMORE DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENTS</u> <u>Carl 2/21/65 Co. Surveyor</u>	
Index File No. <u>T. 3S R. 8W M. 1/4 29 32</u>	Tract or Surv. No. _____ Cor. No. _____