

TILLAMOOK COUNTY REWITNESS

#499

DATE

C 1/4

SECTION

C 1/4 COR.

6

T 3 S

R 9

W., WM.

SEC. 6

HISTORICAL: B-69 SET I. PIPE

BOOK	PAGE	MAPS
4	29	F-20-S B-69
		F-27-30
		B-729
		A-975

CONDITION GOOD

FOUND: 2" I.P. WITH 3" BRASS CAP SET F20-S

CS MAP #


GONE LOCATION IN HWY	6" HEMLOCK	N. 66° 06' W 30'	B-69
GONE LOCATION IN HWY	6" SPRUCE	N 79° 54' W 36'	B-69

COMMENTS:

REWITNESS

I FOUND 2" IRON PIPE WITH 3" TILLAMOOK COUNTY BRASS CAP IN CEMENT SET BY OSHD AFTER REALIGNMENT OF HWY 101.

* 60" Hat Section S. 49° E 3125 FEET



NEW ACCESSORY: DISTANCE TO NAIL WITH BRASS WASHER IN FACE

* 15" HEMLOCK	N 80° E 68' 6"	C 1/4 S6 BTCS

COMMENTS: THIS CORNER IS LOCATED ON THE SE. SIDE OF HWY 101 NEAR THE JCT OF GREEN TIMBER ROAD.

IN THE PRESENCE OF: AL DVORAK DAN MCNUTT

DATE: 9-17-84

PHOTO#:

TITLE

* = County corner tag affixed.