


39 R. 9 W. HEBB County TILLAMOOK  
 Merid. WILL N.F. SIUSLAW State ORE. # 505

CORNER DIAGRAM  


DESCRIBE CORNER MONUMENT FOUND ORIG. POST IS GONE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
 FOUND 23" ALDER, N. 85° E., 23 FT. WITH ORIG. BARK  
 SCRIBE 1/4 SBT.  
 FOUND 10" DEAD ALDER STUB, N. 20° W., 13 FT. WITH OR  
 SCRIBE 1/4 SBT.

PHOTO IDENTIFICATION DATA  
 Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By. \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR BY FEATURES, ALSO HOW TO REACH CORNER  
 THIS CORNER IS LOCATED IN A PLANNED TIMBER SITE  
 FUTURE LOGGING WILL DESTROY THE TWO ORIGINAL  
 ALDER BT'S, THEREFORE I MARK 2 NEW FIR BT'S.

PLANE COORDINATE POSITION  
 State \_\_\_\_\_ Zone \_\_\_\_\_

Prepared By \_\_\_\_\_ Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_ 5680-2

CORNER RECORD (PERPETUATION) # 505

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT  
 SET 1/2" PIPE 12" ABOVE GROUND. MKD. A 4" X 4" FIR LIMB POST 1/4 ON  
 BES. THIS POST SETS ALONGSIDE THE PIPE AND IS 24" ABOVE GROUND.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
 I MARK 2 NEW BT'S:  
 32" FIR, S. 37° E., 30 1/2 FT. MKD. 1/4 S 11 CS BT.  
 30" FIR, N. 89° W., 43 FT. MKD. 1/4 S 10 CS BT.  
 Leonard Whitmore, Tilla. Co. Dep. Surveyor  
 Max Carner, Witness

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

NOTE: Leonard Whitmore is a Deputy County Surveyor qualified to  
 remove monument & re-witness positive old corners found.  
 of Kent Co. Surveyor  
 Whit BT