


INDEX FOREST SERVICE CORNER RECORD (SEARCH) Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_  
 (Ref. FSM 7151.4)  
 Index File No. K-13-14  
 T 35 R. 9W R.D. Hebo County TILLA # 512  
 Merid. Will. N.F. SIUSLAW State ORE.

CORNER DIAGRAM  


DESCRIBE CORNER MONUMENT FOUND  
PROPORTIONED

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
need better identification of what corner it is

PHOTO IDENTIFICATION DATA  
 Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN  
See B-618

PLANE COORDINATE POSITION DATA  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
COPY SENT TO SO

Signature \_\_\_\_\_ Title \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_  
Leonard Whitmore Forestry Tech D. Huber Huber 12-21-72 7100-52 (3)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT  
BRASSCAPPED

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
12" ALDER, S. 73° W., 87 1/4 FT.  
18" ALDER, S. 55° E., 106 1/2 FT.

Work Done By W. PERRY Title R.P.E. Date 1972 State Registration No. 7097  
 or Agency \_\_\_\_\_  
 Certified Cor. Record Prepared?  (Yes) No \_\_\_\_\_ Filed At: TILLA COURT HOUSE Date 1972

REMARKS  
SP 4/72 JLC Carlin  
CS

Index File No. \_\_\_\_\_ T. 35 R. 9W M. \_\_\_\_\_ Tract or Surv. No. 1/256 Cor. No. \_\_\_\_\_