

Index File No. L-13

CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)

Tract or Survey No.

Cor. No.

T 3S R. 9W

R.D. Hebo

County TILLA


#514

Merid. Will.

N.F. SIUSLAW

State ORE.

CORNER DIAGRAM



WITNESS CORNER

DESCRIBE CORNER MONUMENT FOUND

PROPORTIONED

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

OVER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

Signature \_\_\_\_\_

Title Forestry Tech

District Hebo

Headquarters \_\_\_\_\_

Date 12-21-72

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BRASS CAP WITNESS CORNER IS N. 0° 39' 02" E. 49.72 FT. TRUE CORNER.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

20" FIR, N. 36° 50' W., 52 2/3 FT.  
16" ALDER, N. 58° 30' E., 39 5/8 FT.

Work Done By W. PERRY Title R.P.E. Date 1972 State Registration No. or Agency 7097

Certified Cor. Record Prepared?  Yes  No Filed At TILLA COURT HOUSE Date 1972

REMARKS

Spencer J. L. Carlisle  
C.S.

Index File No T 2 R. 9W M. \_\_\_\_\_ Tract or Surv. No. 41 Cor. No. 1