

3 S 3 W N.D. County C.P.B. #521
 Merid. Will N.F. State C.P.B.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
 Caudle 1880 set a Post and marked: (GLO)
 A 30" snag, S 45° E, 47 LKS.
 A 40" snag, N 68° W, 10 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 M. Whitmore 1957 Found a 20" snag, S 45° E, 47 LKS with
 MKS "1/4 SBT" showing.

He found 40" snag, N 68° W, 10LKS with marks rotted off

He marked 2 BTs
 A 18" Alder, S 84° W, 64 1/2 ft Bark scribed 1/4 S 30 BT
 (BT is now a sawed off stump with marks showing).

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 A 14" Alder, N 74° W 71 ft. Bark scribed 1/4 S 19BT. (Now completely
 destroyed by logging).

A Log Road has destroyed the corner point and both original snag BTs.

In using Whitmore's SW Alder as a witness I determined the true
 corner point.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At _____
 Object Ident _____
 Made By _____
 PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____
 Y _____
 Etab. By _____
 Signature _____

Title _____ Division _____ Headquarters Hebo Date 2-15-68(?)

REWITNESS

COWWELL

I SET _____

"x" "x" "Post N.W. feet
 Har Section S. E.

NEW ACCESSORY:

COMMENTS: MEDWINE, LEONARD, WHITMORE ARE (M.W.W.)
 DEPUTY COUNTY SHERIFFS EMPLOYED TO RE-WITNESS
 AUTHENTIC ORIGINAL SURVEY EVIDENCE

IN THE PRESENCE OF: [Signature] Deput County Sheriff
 10/8/80

2° E DEC
 COB° _____

DATE: _____

11 PHOTO#: 2EC
 LITAWOOK CONILA REMITNE?? TITLE _____

* COUNTY corner tag affixed.