


Index File No. R-1
 T 35 R. 9W R.D. HEBO County TILLAMOOK
 Merid. Will. N.F. SUUSLAW State OREGON

CORNER DIAGRAM




DESCRIBE CORNER MONUMENT FOUND GLC 1880 SET POST & MARKED;
 4" VINE MAPLE, S. 71° W., 19 LKS.
 4" VINE MAPLE, N. 45° W., 3 LKS.
 3" VINE MAPLE, S. 10° E., 3 LKS.
 4" VINE MAPLE, N. 23° E., 24 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 2 1/2" BRASS CAP 6" ABOVE GROUND MARKED; OREGON
 STATE BOARD OF FORESTRY 1958 RS 401
 A 4X4 X 30 WHITE POST IS N. 45° E., 3 FT. No. 465.

PHOTO IDENTIFICATION DATA

Photo No. ETJ-5-192
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____



See OTHER SIDE FOR FOUND ACCESSORIES

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 CORNER IS 2 MILES FROM BEAVER ON ROAD S304, THEN
 350 FT. DOWN LEFT FORK OF OLD PRIVATE ROAD.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 By _____
 Agency _____

Signature _____

Title _____

Division _____

Headquarters _____

Date _____

12-7-70

7100-52 (1)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 FOUND 21" DEAD FIR, N. 52° W., 127 FT. WITH VISIBLE SCRIBE MARKS "T3SR10W BT."
 FOUND 11" SPRUCE, N. 60° W., 1 1/4 FT. WITH HEALED WITNESS FACE.

Leonard Whitmore, Forestry tech 12-7-70

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
 SCRIBED 3 NEW WITNESSES; 7-26-78 DISTANCES ARE
 18" ALDER, S. 62° W., 21 1/2 FT. SCRIBED "T3SR10W S 25 FT." To SIDE-CENTER.
 20" SPRUCE, S. 11° E., 29 3/4 FT. " "T3SR9W S 30 BT." VAR. 21°
 12" SPRUCE, N. 86° W., 13 FT. " "T3SR9W S 19 BT."

Leonard Whitmore, Tillamook County Deputy Surveyor 7-27-78
 Index File No. T. 35 R. 9W M. Tract or Surv. No. Sec. Cor. 13c