


Index File No. P-13  
T 3S R. 9W R.D. Hebo County Tillamook Tract or Survey No. No.  
Merid. W. Tillamook N.F. Slauslaw State Oregon



DESCRIBE CORNER MONUMENT FOUND  
Paced north from Section corner common to 21,22,27,28 40' corner. Search area for BT, but could not find any original evidence. The original corner was set by Sam Caudle in 1880. He set a post and scribed a 40" fir snag. M. Whitmore searched for

DESCRIBE BEARINGS TREES OR OTHER ORIGINAL ACCESSORIES FOUND  
corner in 1949, but could find no evidence. There are several snags in the area that would fit Caudle's calls, but they are badly rotted.

A search through the county surveyors records show no record of anyone doing any further work in the area.

I would recommend this corner be reestablished by single proportion.

PHOTO IDENTIFICATION DATA  
Photo No. ETL-6-30  
Filed At: \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Richard L. Bryant 7/31/70

Signature	Title	Division	Headquarters	Date
<i>[Signature]</i>				7/31/70

Set BRASSCAP

PROPORTIONED  
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
18' FIR, N. 40° W. 37<sup>3</sup>/<sub>4</sub> FT.  
10" ALDER, N. 32° E. 36<sup>5</sup>/<sub>8</sub> FT.

Work Done By W. PERRY Title R. P. E. Date 1972 State Registration No. 7097  
Certified Cor Record Prepared?  Yes  No Filed At: TILLA. Date 1972

REGISTERED  
OREGON  
LAND SURVEYOR

JULY 17, 1970  
RICHARD L. BRYANT  
920

*[Signature]* 7/28/70  
C.S.

Index File No. T. 3S R. 9W M. Hebo Tract or Survey No. 1/4 Cor. 21/2