

TILLAMOOK COUNTY REWITNESS # 534

S 24	
S 25	

1/4 COR. SEC. 24
 25 T 3 S R 9 W., WM.

HISTORICAL: 1880	BK. 359	pg. 23	GLO
1888	BK. 10	pg. 61	
1898	Bk. 53	pg. 192	and 164
1956	Map A-688		
1970	Map B-592		

CONDITION FOUND:

Found: A 10" x 12" x 15" stone reported by John Carlich on map A-688, firmly set in a mound of stone, no chisel mks visible


Found: A 7/8" outside Dia. Iron Pipe, painted yellow, and driven alongside the stone. The top was bent over flush with the ground. see map A-688

Gone: A 12' D.F. Snag 54", S 85' W 36.7 ft see Map A-688
 (A Dead Fir 50" Dia. Brs West 53 Lks Dist. BK. 10 pg 61)

COMMENTS:

REWITNESS

1 SET A 1 1/2" x 30" IRON PIPE with Brass Cap
 in Concrete, in a mound of Stone.
 * 60" Hat Section 15 East



NEW ACCESSORY:

- * 16" Dia. Douglas Fir Bears N 48° E 57.14 ft
 Scribed "1/4 S 24 BT CS" (to face)
- * 14" Dia. Douglas Fir Bears S 18 1/2° E 31.87 ft
 Scribed "1/4 S 25 BT CS" (to face)

COMMENTS: The 1/4 corner depicted by Map B-592 Bears N 39° E 15.80 ft and BT's for Map B-592 Bears as follows: 14" Douglas Fir N-31 1/2° E 56.90 ft and a 24" Douglas Fir S 19° W 171.24 ft, from my Corner Position.

IN THE PRESENCE OF: Gale Arthur
 DFTerry Jones

DATE: 4/10/81

PHOTO# REC

* = County corner tag affixed.

TILLAMOOK COUNTY COMPLEX BEARINGS TITLE