

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. Non

Index File No. V-21 County TILLAMOOK # 535

T 3 S R. 9 W R.D. HEBO State ORE

Merid. WILL. N.F. SILUSLAW

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLA 1880 SET POST.

4" VINEMAPLE, S. 85°W, 25 LKS.
 4" VINEMAPLE, N. 5°W, 100 LKS.
 3" VINEMAPLE, S. 80°E, 13 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

REGISTERED SURVEYOR, JOHN CARLICH 1956, SET 4x4x60 CHERRY POST AND SCRIBED;
 15" FIR, S. 74°W, 21.84 FT.
 14" FIR, N. 26°E, 41.84 FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

LAND SURVEYOR, FREDRICK GAYLORD IN 1974 SET 3/4" IRON ROD IN REMAINS OF CARLICH POST.

PLANE COORDINATE POSITION

State _____ Zone _____

Signature Leonard Whitmore Title Forestry Tech Division Ligler Headquarters Hebo Date 2-8-77 7100-52-13

REWITNESS

1 SET DOWN

"x" "x" "x" Post N.W. feet
 "x" "x" "x" Har. Section S. E.

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF:

DATE: _____

PHOTO: _____

* = County corner tag affixed.

TITLE _____