

INDEX CORNER RECORD SERVICE

Index File No. V-16 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. Cor. No. V-16

T 3 S. R. 9 W R.D. HERO County TILLAMOCK **#538**

Merid. Will. N.F. SIOU SLAW State ORE.

CORNER DIAGRAM
See A-674

DESCRIBE CORNER MONUMENT FOUND BY RECORD JOHN CARLICH ORLS # 287 SEPT. 1955 SET BY PROPORTIONMENT A 4 X 4 X 48 HEMLOCK POST AND MARKED 2 WITNESSES: 8" HEM., S. 35° W., 9/10 FT. SCRIBED 1/6 BT # 287 26" HEM., N. 45° W., 5 2/3 FT. SCRIBED 1/6 BT # 287

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
Post is gone.
FOUND 14" HEM., S. 35° W., 9/10 FT. WITH HEALED WITNESS FAC I CHOPPED OPEN ENOUGH TO EXPOSE SCRIBE MKS. "BT" FOUND 26" SAWED OFF HEM. STUMP, N. 45° W., 5 2/3 FT. WITH SCRIBING ROTTED OFF.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA
Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA
State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature *Title* *Date* *Headquarters*
Leonard Whitmore Forestry Tech Timber Herbo 11-27-70 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
Set 1/2" GALV. Pipe 18" ABOVE GROUND IN ROOTS OF A HEMLOCK.
Set ALUMINUM POST ALONGSIDE WITH "PENALTY TO DESTROY" SIGN ATTACHED.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE.
I MARK 27" SPRUCE, S. 79° E., 28 FT. SCRIBED E 1/6 S 34 BT.

Leonard Whitmore, Tillam. Co. Deputy Surveyor.
11-27-70

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS