

Index File No. **G-4**


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. **#573** Cor. No.

T. **3S** R. **10W** R.D. **HEBO** County **TILLA.**

Merid. **WILL.** N.F. **SIUSLAW** State **ORE.**

CORNER DIAGRAM




DESCRIBE CORNER MONUMENT FOUND

W. E. ANDERSON, TILLAMOOK COUNTY ENGINEER, 1951
SET 4X4 CEDAR POST, & MARKED;
10" HEM, N. 10° E., 56 3/4 FT.
16" HEM, S. 85° E., 85 1/2 FT.
8" HEM, S. 50° E., 23 3/4 FT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 1" PIPE WITH LEADED CAP MARKED
FOUND 22" HEM, S. 85° E., 85 1/2 FT. VISIBLE
SCRIBING FOUND ON ROTTED FACE.



THE OTHER TWO BT'S WERE DESTROYED BY LOGGING.

Leonard Whitmore 10-15-76

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature *Leonard Whitmore* Title *Forestry tech* Division *Timber* Headquarters *Hebo* Date *12-17-76* 7100-52 (3)

REWITNESS

I SET

"x" "x" " Post N.W. feet
 " Hat Section S. E.

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF:

DATE:

PHOTO#:

TITLE

County corner tag affixed.