


REVISION 1976

Index File No. C-9
T. 3 S R. 10 W
Merid. W.M.

CORNER RECORD (SEARCH)
(Ref: FSM 7151.4)
Tract or Survey No. #588
R.D. Hebo County TILLAMOOK
N.F. SIUSLAW State ORE.

Cor. No.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT

GLO 1933 SET BRASS CAP & MARKED:
48" HEM., S. 10° E., 100 LKS.
40" HEM. S. 24° W., 6.5 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1-29-63 I MARK A 14" HEM., S. 5° E., 39 LKS. SCRIBED
1/4 S4 BT
CORNER IS LOCATED ON 15' X 8' EARTH MOUND ON WEST SIDE OF A CREEK RUNNING S.E.

PHOTO IDENTIFICATION DATA

Photo No. ETJ-5-1363
Filed At.
Object Ident. DIRECT
Ident. By L. Whitmore
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH

REVISION 1976

PLANE COORDINATE POSITION DATA


State _____ Zone _____
Signature Leonard Whitmore

FOUND ORIG. S.E. BT IS A SAWED-OFF ROTTED STUMP
ORIG. S.W. BT IS GONE.
FOUND MY 1963 BT NOW 24" HEM. WITH HEALING
WITNESS: FACO Forestry Tech Timber Division #121116 Headquaters Hebo

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 1933 GLO BRASS CAP.



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I SCRIBE A NEW BT:
11" FIR, N. 32° W., 14' FT. MARKED 1/4 S5 BT. DISTANCE TO SIDE-CENTER VAR. 21"

Signature Leonard Whitmore, Tillamook Co. Deputy Surveyor.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS

File No. _____ T. 3 S R. 10 W M. Tract or Surv. No. 1/1 Cor. 5/4 13