


Index File No. **A-5** CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____
 T. **B S** R. **10W** R.D. **HEBO** County **TILLAMOOK** # **593**
 Merid. **W. M.** N.F. **SUSLAW** State **ORE.**

CORNER DIAGRAM


DESCRIBE CORNER MONUMENT FOUND **GL 1933 SET BRASS CAP & MARKED:**
14" HEM, S. 15° E., 53 LKS.
16" HEM, S. 62° W., 27 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 1X2" WOOD STAKE FOR CORNER POINT.
FOUND 4"X4" WHITE POST 1 FT. S.W. OF STAKE.
FOUND BOTH BT STUMPS WITH SCRIBES SHOWING THE BT'S ARE IN PROPER BEARINGS AND DISTANCES FROM STAKE.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____ Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Logging MAY HAVE DESTROYED THE BC.
I SET IRON FENCE POST AT CORNER POINT AND ATTACH "ATTENTION" SIGN. Headquarters **Hebo** Date **3-3-76**
 Signature _____ Title _____ Division _____
Leonard Whitmore Forestry tech Timber
 Estab. By _____ Agency _____

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____

REWITNESS

I SET _____
 "x" "x" " Post N.W. feet
 " Hat Section S. E.

NEW ACCESSORY:

| | | |
|--|--|--|
| | | |
| | | |
| | | |
| | | |

COMMENTS: _____

IN THE PRESENCE OF: _____

DATE: _____ PHOTO#: _____ TITLE _____

* = County corner tag affixed.