


TILLAMOOK COUNTY REWITNESS

#598

N. 17 SEC. 8
1/4 COR. 17 T 35 R 10 W., WM.
S. 8



HISTORICAL: GLO-1882-SET POST-B.T.S.

MAP F-14-24 O.S.H. Dept. Found 1/4 cor. 1936

MAP B-97 W.E. Anderson Co. Surveyor Found 1/4 cor. 1947

MAP F-28-18

Book 3 Page 168-169 = Book 2 Page 560

Tillamook Co. Deputy Surveyor Leonard Whitmore

U.S. Forest Service. Fd original B.T.S.

CONDITION

FOUND: 4x4 Post 12" above ground with tack

FOUND REMAINS (1971)	18" Hem S5°W 17"	GLO	1882
UNDER RD FILL (1971)	16" Hem N27°E 44"	GLO	1882
GONE (1971)	5" Fir S69°30'E 19"	Book 3 Page 1689	1963
UNDER RD FILL (1971)	4" Fir N59°30'E 26"	Book 2 Page 560	1963
(1971) Fd Brass Cap by County & Fd a 1" I.P.			
Found in Field (1971)	5" CHITUM S38°W 825'	has U.S. Forestry tag	

(1968) Found 3/4" Iron Pipe 12" above ground at same position

COMMENTS: as 4x4 Post.

REWITNESS

CEMENT & 8" TILE (1971)


1 SET 1/4" Iron Pipe - 30" in length - with brass Cap at Corner

feet

* 84 " Hat Section South 15

NEW ACCESSORY:

5" Fir N70°W 22 1/2"	← INCORRECT BEARING
8" Fir N84°E 20 6/8"	← INCORRECT BEARING
10" Fir S85°W 20 6/8"	Scribing visible
7" Fir S08°E 22 7/8"	Scribing visible



COMMENTS: Corner is South & Western of Cape Lookout County Road. Corner is located at base of a 60 foot fill.

IN THE PRESENCE OF:

Gale Arthur

1971 Gale Arthur

2' E

George W. Urvey

Roger Knippel

COB

1" PHOTO: SEC

1971
DATE: 1968

TILLAMOOK COUNTY DEPT. OF LAND

TITLE

* = County corner tag affixed