


Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: *Post*

#622

SET BY COUNTY SURVEYOR

5. Investigation Notes:

Find the corner post lying upon the ground.

Find 8 in. pine N. 28 1/2° E., 3 ft. with visible scribing 1/6 BT.

Find 12 in. pine S 23 1/2° E., 32 3/4 ft. with visible scribing BT.

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic

Needs Verif. Monument

For estab. Survey

Status *DRILL - N.F.*

6. Signed *L. Whitmore* Title *Forestry aid* Date *1-21-61*

PERPETUATION RECORD

10. Monument:

Set 1 inch pipe into ground at corner location

11. Accessories

Put location posters on above mentioned bearing trees.

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:

The corner is located 30 ft. west of an sand road intersection.

L. Whitmore is a deput. Co Surveyor qualified to be witness positive old monuments

L. Whitmore

9/16/70 J. Harker Co Surveyor

D. Derrick