

1. T. 3 S. R. 10 W. No. 17 R. Cor. Sec. Mer. Will. State. Ore. N.F. Siuslaw Dist. Hebo

2. Corner Status

22	23
27	26

3. Original Description Vol. Page Where recorded #632

4. Description of Corner: 1882
 Post MKd. T3SS23 on N.E., R10WS 26 on S.E., S. 27 on S.W., S on NW, with 2 Notches on S. and E. edges

5. Investigation Notes:
 Post gone.
 Dead fir 36 in., S. 20° W., 34 LKS., MKd. S BT

7. PHOTO IDENTIFICATION
 Photo No. _____
 Taken By: _____

Plane Coordinate Position Data
 Date _____ Zone _____

Est. By _____
 Field Book No. _____
 Where Filed _____

9. EVALUATION
 Authentic _____
 Needs Verif. Manum.
 Re-Est. _____ Survey _____
 Land Status NF

6. Signed L. WHITMORE Title forester aid Date 4-21-60

*See map, volume of records, C. L. Dept. Land Survey
 empowered to re-locate old original G.C. corner
 K. R. C. S.
 9-118/78*

11. ACCESSORIES
 FIR 40 in., S. 20° W., 34 LKS., MKd. T3SR10WS 27 BT
 EIK brush, 5 in., S. 42° E., 25 LKS. MKd. T3SR10WS 26 BT
 EIK brush 4½ in., N. 10° W., 62 LKS. MKd. T3SR10WS 22 BT
 EIK brush 4½ in., N. 15° E., 75 LKS. MKd. T3SR10WS 23 BT

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) _____ (City) _____ (County) _____ (State) _____

14. REMARKS:
 New BTs {
 FIR 22 in., S. 30° W., 26½ LKS., MKd. T3SR10WS 27 BT
 FIR 22 in., S. 63½° E., 23 LKS., MKd. T3SR10WS 26 BT
 FIR 12 in., N. 44° E., 25 LKS., MKd. T3SR10WS 23 BT
 FIR 12 in., N. 28° W., 15½ LKS., MKd. T3SR10WS 22 BT
 Set fir limb post (not MKd)
 BY M.W. 3-20-52