


T 3 S R 10 W No. 17 P Cor. 1/4 Mer. Will. State Ore. N.F. Sluslow Dist. Hebo

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where recorded

4. Description of Corner: 1882
Hemlock 10in. for 1/4 sec. cor. MKd. 1/4 S on W. face #634

5. Investigation Notes:

old hemlock stump 48in. above ground with scrie mark for original corner.

7. PHOTO IDENTIFICATION

Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Est. By _____
Field Book No. _____
Where Filed _____

9. EVALUATION

Authentic _____
Needs Verit. _____ Manum.
Re-Est. _____ Survey _____
Status NF

6. Signed L. Whitmore Title Forester Aid Date 4-21-60

10. MONUMENT

NOTE Leonard Whitmore is a Deputy County Surveyor qualified to Re-witness & Re-Monument POSITIVE old monument Found

11. ACCESSORIES

Phelan County Surveyor 9/17/71
Hemlock 6in., S. 7° E., 12 LKS., MKd. 1/4 SBT
Hemlock 8in., N. 72° E., 10 LKS., MKd. 1/4 SBT

Field Book _____ Page _____

12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) (City) (County) (State)

14. REMARKS:

FIR 30in., N. 5° W., 26 LKS., MKd. 1/4 S 22 BT
New BT's FIR 20in., S. 10° E., 60 LKS., MKd. 1/4 S 23 BT
The corner sets 6 1/2 chains E. of a brook, 3 LKS. wide runs N.

BY M.W. 3-21-52