

35 R. 10W 3.D. HeBO County
 Will N.F. SIUSLAW State CRE #638

INNER DIAGRAM DESCRIBE CORNER MONUMENT FOUND

29 ⊗ 28
 1/4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 45" FIR, N. 80° W, 74¹/₂ FT. AS ORIG. NOTES. SAWED INTO THIS TREE AND FOUND VISIBLE MKS. 1/4 S B. THE ORIG. 10" HEM., N. 10° E, 80¹/₂ FT. IS ENTIRELY GONE. A CREEK IS 1.25 CHAINS NORTH AS IN ORIG. NOTES.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature _____ Title _____ Date _____ Headquarters _____
 Leonard Whitmore Tilla Co. Dep. Surveyor Hebo 1/16-67 5680

REWITNESS

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 SET 1" pipe 30" ABOVE GROUND

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 I MARK one New BT:
 16" Hem. S. 30° E., 13 FT. MKD. 1/4 S 28 C S BT.
 LEONARD WHITMORE, TILLA CO. DEP. SURVEYOR
 JIM ROGERS WITNESSES
 FRANK FERGUSON

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At. _____ Date _____

REMARKS
 NOTE LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR QUALIFIED TO RESET & REWITNESS OLD CORNERS FOUND FOR CORNERS.

DATE: _____ PHOTO#: _____ TITLE _____

County corner tag affixed.