

USDA-FOREST SERVICE 117

Index File No. **S-3**

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No.

Cor. No.


T. **35** R. **10W** S. **10** R.D. **HEBO** County **TILLAMOOK**

#641

Merid. **WILL.** N.F. **SIVSLAW** State **ORE.**

CORNER DIAGRAM

CN $\frac{1}{16}$



DESCRIBE CORNER MONUMENT FOUND

W. A. ANDERSON, TILLAMOOK COUNTY ENGINEER, 1956
SET 2" IRON PIPE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 2" IRON PIPE 22 FT. EAST OF THE EAST SIDE
HARD TOP SHOULDER OF SAND BEACH CAMPGROUND
ROAD.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION

State _____ Zone _____
X _____
Y _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET IRON FENCE POST 1 FT. NORTH OF CORNER - ATTACH PROPERTY
BOUNDARY SIGN.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SCRIBE 2 PINES: VAR. 21°
4" PINE, N. 18° E., 120 FT. SCRIBED " $\frac{1}{16}$ BT. " DISTANCES ARE TO SIDE
4" PINE, S. 1° E., 16 $\frac{1}{4}$ FT. SCRIBED "CN $\frac{1}{16}$ BT. "

Leonard Whitmore, Tillamook County Deputy Surveyor, 12-14-76

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index No. T. **35** R. **10W** M. Tract or Surv. No. **Sec** Cor. **30**