

CORNER RECORD (SEARCH)

Tract or Survey No. X-9 Cor. No. X-9

File No. 35 R. 10W R.D. Hebo County TILLAMOCK # 644

Merid. NAD N.F. SUSLAW State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

GLO 1884 SET POST AND MKD:
 24" Hem, S. 35° W., 22" FT.
 16" Hem, N. 22° E., 40" FT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Post is gone.
 FOUND 25" Hem, STUB, N. 22° E., 41 FT. WITH NARROW OPEN FACES
 MARK "S" SHOWING.
 FOUND 24" ROTTED Hem. STUB, S. 35° W., 22" FT. WITH MARK
 "1/4" SHOWING.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____ Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO RE

Signature: Leonard Whitmore Title: Forestry Tech Division: Tillamook Headquarters: Hebo Date: 1-18-68

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

I SET 1" PIPE 36" ABOVE GROUND.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I MARK 2 NEW BT'S:
 42" SPRUCE, S. 76° W., 20" FT. MKD. 1/4 S 32 BT CS
 38" SPRUCE, N. 78° E., 33 FT. MKD. 1/4 S 33 BT CS

Leonard Whitmore, Deputy Till. Co. Surveyor

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
 LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR
 EMPOWERED TO RE-WITNESS CERTAIN CORNER
 MONUMENTS