


LAND CORNER RECORD

T. 3 S. R. 10 W. No. 215 Cor. 4 Mer. Will State ORE. N. F. SLUSLAW Dist. Hebo

Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded #645
4. Description of Corners:



50 has copy

5. Investigation Notes:

FOUND 4"X4" FIR POST 24" ABOVE GROUND (ORIG 1879) WITH MKS. 1/4 ON SOUTH SIDE.

FOUND 2 BT'S ESTABLISHED 1958 BY M. WHITMORE. 18 IN. SPRUCE, N. 82° W., 86 1/2 FT. WITH HEALED WITNESS BLAZE.

18 IN. ALDER, S. 74° E., 25 FT. WITH BARK SCRIBE 1/4 S 3 BT.

Photo Identification

Photo No. _____

Phot. By: _____

Plane Coordinate Position Data

Latitude _____ Zone _____

Tab. By _____

Field Book No. _____

Where Filed _____

Monument _____

Established _____ Monument _____

Established _____ Survey _____

Corner Status _____

6. Signed L. WHITMORE Title FORESTRY TECH Date 5-16-63

PERPETUATION RECORD

10. Monument:

MEROIN WHITMORE WAS A DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENTS.

11. Accessories

2/21/63 J. L. Carr Co Surveyor

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ Volume _____ Page _____

License _____ Agency _____ Date _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: By COMPASSING AND CHAINING M. WHITMORE 1958 FOUND THE ORIGINAL CORNER POST STILL STANDING IN SOUND CONDITION WITH VISIBLE MKS. 1/4 ON THE SOUTH SIDE, A FALLEN SNAG RESTS ACROSS THE TOP OF THE POST.