


USDA FOREST SERVICE  
 Index File No. A-19 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_  
 T 4 S R. 8 W R.D. HEBO County TILLAMOCK #659  
 Merid. WILL. N.F. SIUSLAW State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT ~~FOUND~~ GLO 1933 SET BRASSCAP & MKD;  
8" FIR, N. 69° 15' W., 134 LKS.  
8" FIR, S. 10° 45' W., 97 LKS.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
M. WHITMORE, 1960 COULD NOT FIND THE BRASSCAP ASSUMING IT WAS OBLITERATED BY A ROCK SLIDE. HE FOUND BOTH THE NW AND SW BT'S. THE SCRIBED SIDES DO NOT FACE THE CORNER. HE SET 3/4" PIPE AT BASE OF A 5 FT. PERPENDICULAR BLUFF.


PLANE COORDINATE POSITION

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
B-2-76 I FOUND BOTH BT'S Now 30" IN DIAMETER. HEALED WITNESS FACE AND SNOW BLAZE SHOWS EX. BOTH. THE WITNESS FACE OF THE SW BT FACES WEST WITH SCRIBED MARK "2" SHOWING. THE FACE OF THE NW BT FACES SOUTH. I CAN FIND NO TRACE OF THE GLO OR WHITMOR'S PIPE. I CALLED BLM, he found to verify the original survey notes against ours. The notes are correct.

Signature: [Signature] Title: \_\_\_\_\_  
 Division: \_\_\_\_\_  
 Headquarters: \_\_\_\_\_  
 Date: 8-3-76  
 (89/1) 25-012 7100-52 (3/68)

I SET



"x" "x" " Post N.W. feet  
 " Hat Section S. E.

NEW ACCESSORY:


COMMENTS: \_\_\_\_\_

IN THE PRESENCE OF: \_\_\_\_\_

DATE: \_\_\_\_\_  
 PHOTO#: \_\_\_\_\_  
 TITLE \_\_\_\_\_

\* = County corner tag affixed.