


LAND CORNER RECORD

(Rectangular)

1. T 4S R 8W No. C-1 Cor. # Mer. WILL State OREGON N.F. SIUSLAW Dist. HeRo



3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: POST - UNMARKED #665

5. Investigation Notes: REMAINS OF OLD POST SUPPORTED BY PIPE  
 REMAINS OF FIR STUMP - No. MARKS - N79°E - 62 LKS  
 FIR STUMP - No MARKS - N28°W - 81 LKS

7. Photo Identification  
 Photo No. \_\_\_\_\_

8. Plane Coordinate Position Data  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
 Field Book No. \_\_\_\_\_  
 Where Filed \_\_\_\_\_

9. Evaluation  
 Authentic   
 Needs Verif.  Monument   
 Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
 and Status Pub. Rec. - N.F.

6. Signed Mer. Corner Title Forestry Aide Date 5-18-60

PERPETUATION RECORD

10. Monument: use original post of which is in a fair state of preservation.

11. Accessories new BTs.  
 20 in. for N. 34°W, 19 ft. scribed T4SR9WS12BT  
 20 in. for N. 53°E, 12 ft. scribed T4SR8WS7BT  
 18 in. for S. 39°E, 5 ft. scribed T4SR8WS18BT  
 20 in. for S. 40°W, 40 ft. scribed T4SR9WS13BT  
 Nail bearing tree signs on said BTs.

12. Set By \_\_\_\_\_ Title \_\_\_\_\_  
 License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ (Agency) \_\_\_\_\_  
 (Date) \_\_\_\_\_ (City) \_\_\_\_\_ (County) \_\_\_\_\_ (State) \_\_\_\_\_

14. Remarks:  
 This corner is south 50 ft. from the head of a canyon bearing north.  
 Witnessed by Leonard Whitmore, deputy surveyor  
 Robert means, forestry aid  
 Mervin Whitmore