

CORNER RECORD (SEARCH)

Index File No. _____ Tract or Survey No. _____ Cor. No. A-17
 T 4S R. 9W R.D. HeBo County TILLA # 680
 Merid. Will N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLO 1906 SET FOR A CLOSING CORNER A 13 X 10 X 8 4" ABOVE GROUND WITH MKS CC ON S., 4 GROOVES ON W., 2 GROOVES ON E. SIDES AND 4 ON TOP.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
I FOUND THE ABOVE DESCRIBED STONE IN PLACE WITH A 3/4" GALV. PIPE 24" HIGH SET ON E. SIDE OF STONE.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
THIS CORNER IS LOCATED IN A THICK VIXEMAPLE AND SALMONBERRY JUNGLE. A SMALL CR. IS 10 FT. SOUTH

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____ Agency _____

AS NO WITNESSES WERE AVAILABLE IN SECS. 2 OR 3 I MARK A 33" SPRUCE, DUE EAST, 75 FT. CCTHS R9W S2 BT CS. Leonard Whitmore, Tilla. Co. Sup. Surveyor, 4-8-69

SPRAY RED PAINT ON STONE, PIPE, FACE OF WITNESS AND A BAND AROUND WITNESS TREE.

Signature Leonard Whitmore Title Forestry tech Division Timber Headquarters Nebo Date 4-8-69 7100-52 REV. 65 5

REWITNESS

I SET _____

"x" "x" " Post N.W. feet
 " Hat Section S. E. 61

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF: _____

DATE: _____

PHOTO#: 2EC

TITLE _____

* = County corner tag affixed.