

CORNER RECORD (SEARCH) PRODUCT OF Survey No. Cont. No. A-17

Index File No. T 4S R 9W R.D. HEBO County TILLA #681
 Merid. Will N.F. SLUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND- GLO 1906 SET FOR A CLOSING CORNER A 13 X 10 X 8. 4" ABOVE GROUND WITH MKS CC ON S., 4 GROOVES ON W., 2 GROOVES ON E. SIDES AND + ON TOP.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
I FOUND THE ABOVE DESCRIBED STONE IN PLACE WITH A 3/4" GALV. PIPE 24" HIGH SET ON E. SIDE OF STONE.

PHOTO IDENTIFICATION DATA
 Photo No.
 Filed At.
 Object Ident.
 Ident. By Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
THIS CORNER IS LOCATED IN A THICK VINE MAPLE AND SALMONBERRY JUNGLE. A SMALL CR. IS 10 FT. SOUTH

PLANE COORDINATE POSITION DATA
 State Zone
 X
 Y
 Estab. By Agency

AS NO WITNESSES WERE AVAILABLE IN SECS. 2 OR 3 I MARK A 33" SPRUCE, DUE EAST, 75 FT. CCTHS R9W S2 BT CS. SPRAY RED PAINT ON STONE, PIPE, FACE OF WITNESS AND A BAND AROUND WITNESS TREE.

Signature Leonard Whitmore Title Forestry tech Division Timber Headquarters Hebo Date 4-8-69 7100-52 REV. 65 5

REWITNESS

COMMENTS:

1 SET

"x"	"x"	Post	N.W.	feet
" Flat Section			S. E.	

NEW ACCESSORY:

COMMENTS: County Surveyor's Office
RE WITNESS ANTIMONY

IN THE PRESENCE OF:

DATE: 2° E' DEF'
 COB'
 PHOTO# SEC'
 LIGGYWOOD CONNLY BEWILDERE TITLE

County corner tag affixed.