

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. E-19

File No. 4S R. 9W R.D. HEBO County TILLA. **#683**

Merid. Will. N.F. SIUSLAW State ORE.

CORNER DIAGRAM

2

DESCRIBE CORNER MONUMENT FOUND

GLD 1898 SET ALDER POST + MKD.
14" FIR, N. 32° W., 29 LKS.
10" ALDER, S. 9° 30' E., 42 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Post is gone.
Found 18" ALDER, S. 9° 30' E., 42 LKS. WITH HEALED WITNESS FACE. I CHOPPED OPEN AND FOUND A DECAYED FACE BUT FOUND THE LETTER "B" ON THE FILL WOOD THE ORIG. N.W. BT IS ENTIRELY GONE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

AS THIS AREA WILL SOON BE LOGGED I MARK 2 WITNESS TREES.
I DETERMINE THE COR. POINT USING THE RECORDED BEARING AND DISTANCES FROM THE ORIG. S.E. ALDER.

PHOTO IDENTIFICATION DATA

Photo No. EIJ-7-225
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature: Leonard Whitmore Title: Forestry Tech Division: Timber Headquarters: Hebo Date: 5-12-69 752 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT.

I SET 3X3X24 LIMB POST MKD. 1/4 S ON NORTH SIDE.
SET ALUMINUM POST WITH LOCATION POSTER 2 FT. N.E. OF POST.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New BT'S:
45" FIR, N. 4° 30' W., 15 1/2 FT. MKD. 1/4 S 2 BT CS.
48" FIR, S. 59° W., 84 1/2 FT. MKD. 1/4 S 11 BT CS.

Leonard Whitmore, Tilla. Co. Dep. Surveyor

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

PAINT RED BAND & PUT BT SIGNS ON WITNESSES
NOTE Leonard Whitmore, a DEPUTY COUNTY SURVEYOR qualified to PERFORM RE-MONUMENT POSITIVE CORNER MONUMENT FOUND
JL Smith County Surveyor 5/11/69