


#684

T. 4 S. R. 9 W. W. 11 Mer.

(Make sketch of township near Corner and show section line markers thus "X")



Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ Chains.

Section line marker between Secs. _____ and _____ is on _____ on the _____ (Name of road, trail, etc.) located _____ (Tree, post, etc.)

Chains H, F, M, S, from Sec. Cor; 1/4 (M); 1/2 (F); 3/4 (H); 1 (S). Give any further facts needed to find Corner again:

On top of high water. H. S. 3.

WERU WHITMORE WAS A DEPUTY COUNTY SURVEYOR EARLIER TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENTS

2/6/16 of P. Conlides

U. S. GOVERNMENT PRINTING OFFICE 16-12726-1

Form 874-9—Revised November 1939
U. S. Department of Agriculture
FOREST SERVICE

CORNERS OF THE PUBLIC SURVEY

T. 4 S. R. 9 W. W. 11 Mer.

Corner common to Sections 3, and 4

Corner consists of a Original Post (not) in place

State condition good

Dimensions above ground 24 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

N	1/4	1/4	1/4	1/4					
W	4	4	3	3					
S									
E									
NW									
SW									
SE									
NE									

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4	5/4	1/4	5/3
5/7		5/7	

Species Pin. strob. Pin. strob.

Diameter 40" 40"

Bearing N. 83° W. S. 23° E.

Distance 665 Lks. 49 Lks.

Do you believe this to be a genuine Land Office Corner? Yes
If not, why?

Mason H. H. H. H.
(Signature)

Feb. 1953
(Date)

P. Conlides
(Title)

16-12726-1

4.5.9W W. 11 Cor 3 and 4