


Index File No. **C-5** CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. **#686** Cor. No. **686**

T. **45** R. **9W** R.D. **Hebo** County **TILLA** State **ORE.**

Merid. **WLL** N.E. **SINSLAW**

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT ~~ESTABLISHED~~ **GLO 1898 USED 10" ALDER FOR CORNER POINT & MARKED; 6" ALDER, N. 49 1/2° E, 17 LKS. 10" ALDER, S. 59 1/2° W, 19 LKS.**

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND THE ORIGINAL CORNER TREE NOW 22" IN DIAMETER WITH HEALED FACES ON THE EAST AND WEST SIDES.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOUND 12" ALDER, N. 49 1/2° E, 11 1/2 FT. WITH HEALED WITNESS FACE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOUND 22" ALDER S. 58 1/2° W, 12 1/2 FT. WITH HEALED WITNESS FACE.

PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____
 Y _____

ATTACH BEARING TREE SIGNS AND PAINT RED BAND AROUND WITNESSES.
 ATTACH "PENALTY" ^{TO} DESTROY SIGN ON CORNER TREE

Established By **Leonard Whitmore** Signature **Forestry Tech** Title **Forestry** Department **Nebo** Headquarters **Nebo** Date **5-2-72** 7100-52 1

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
LEONARD WHITMORE IS A DEPUTY COUNTY SHERIFF THE EMPLOYEE TO RE-WITNESS POSITIVE EVIDENCE OF NEW MONUMENTS

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
CORNER IS ON NORTH SLOPE 70 FT. NORTH OF A RIDGE RUNNING E-W.

215th St. I. Cal. _____

File No. T. **45** R. **9W** M. Tract or Surv. No. **14** Cor. **615**