


Index File No.	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No.	Cor. No. <u>J-1</u>
T. <u>4S</u> R. <u>9W</u>	R.D. <u>Hebo</u>	County <u>TILLA.</u>	<u>#687</u>	
Merid. <u>Will.</u>	N.F. <u>SIUSLAW</u>	State <u>ORE.</u>		
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND ^{FOUND} <u>POST & FOR A WITNESS THE</u>			
	<u>GL 1898 SET ALDER</u>			
	<u>NE. BT of THE STANDARD COR. To SECS. 12-13 T4S R10W.</u>			
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND ²			
	<u>FROM THIS CLOSING CORNER THE ABOVE MENTIONED</u>			
	<u>BT SNA9, IS N. 56° 30' E., 200 LKS.</u>			
	<u>M. WHITMORE, USFS, 4-17-53 SET A POST & MKD.</u>			
	<u>14" ALDER, S. 59° E., 41 FT. SLOPE DIST. MKD. T4S R10W S18BT.</u>			
	<u>12" ALDER, N. 40° E., 38 FT. SLOPE DIST. MKD. T4S R10W S18BT.</u>			
PHOTO IDENTIFICATION DATA	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER			
Photo No. _____	<u>PAINT RED BAND & PUT BT SIGNS ON WITNESSES.</u>			
Filed At. _____	<u>WHITMARES BT'S ARE FOUND AS IN HIS RECORDS:</u>			
Object Ident. _____	<u>THE STANDARD CORNER To SECS. 12-13 IS 87 LKS.</u>			
Ident. By _____	<u>SOUTH.</u>			
PLANE COORDINATE POSITION DATA				
State _____ Zone _____				
X _____				
Y _____				
Estab. By _____				
Signature <u>Leonard Whitmore</u>	Title <u>Forestry Tech</u>	Division <u>Timber</u>	Headquarters <u>Hebo</u>	Date <u>5-13-69</u>
Agency _____	7100-52 (3/68)			

No additional information

LEONARD WHITMORE IS A LICENSED SURVEYOR EMPOWERED TO SET AUTHENTIC ORIGINAL MONUMENTS
 Tilla County Surveyor