

T. 4 S. R. 9 W. No. 6-5 Cor. 1/2 Merrill State ^(Rectangular) ORE. N. F. SIUSLAW Dist. HERB

Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded #688

4. Description of Corners:
alder post

5. Investigation Notes:
past gone.
Found 20 in. alder S. 62°30'E., 23 1/2 ft. with axe blow inside of partially healed over scar.
Found 18 in. alder S. 74°30'W., 31 1/2 ft. with witness scar on outside. (did not cut open).
These alder are in their proper distance and bearing as of the original field notes thus establishing the corner point.

6. Signed M. Whitmore Title Surveyor Date 4-7-61

Photo Identification
Photo No. _____
Ident. By: _____

Plane Coordinate Position Data
State _____ Zone _____

Established By _____
Field Book No. _____
Where Filed _____

Evaluation
Authentic
Leads Verif. Monument
Established Survey
Status N. F.

PERPETUATION RECORD

10. Monument:
set a fir limb post 4" x 4" x 36" dia. and built a rock mound with a 2 ft. base 1 ft. high around the post.

11. Accessories new BT:
9 in. fir, N. 15° W., 55 ft. mkd. 457 BT
14 in. fir, N. 40° 30' E., 65 ft. mkd. 458 BT

NOTE: I hesitate to endorse this as a witness - not enough data given on the original

12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:
By M. Whitmore
Leonard Whitmore is a Deputy County Surveyor qualified to Re-witness & Re-monument POSITIVE old monuments found
9/17/71