

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. **# 690** Cor. No. **J-1**
 Section No. **J-1** R. **9** W.R.D. **Hebo** County **TILLA** State **ORE.** **UPDATED 1976**
 Secid. **Will** N.F. **SIUSLAW**

FORMER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
GLO 1898 SET ALDER POST & FOR A WITNESS THE NE BT OF THE STANDARD COR. TO SECS. 12-13 T4S R10W.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FROM THIS CLOSING CORNER THE ABOVE MENTIONED BT SNA9, IS N. 56° 30' E., 200 LKS. M. WHITMORE, USFS, 4-17-53 SET A POST & MKD; 14" ALDER, S. 59° E., 41 FT. SLOPE DIST. MKD, T4S R10W S1 BBT. 12" ALDER, N. 40° E., 38 FT. SLOPE DIST. MKD, T4S R10W S1 BT.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Taken At _____
 Subject Ident. _____
 Taken By _____
 Signature _____

PLANE COORDINATE POSITION
 State _____ Zone _____
 Established By _____ Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PAINT RED BAND & PUT BT SIGNS ON WITNESSES. WHITMORES BT'S ARE FOUND AS IN HIS RECORDS. THE STANDARD CORNER TO SECS. 12-13 IS 87 LKS SOUTH. Leonard Whitmore 5-13-69 (OVER)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVID

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS
FOUND PIPE AND BT'S IN PROPER POSITION. CORNER IS ON EAST EDGE OF SCARIFICATION.
L. Whitmore, 4-13-76