

T 4 S R 9 N No. 49 Cor. 1/4 Mer. Will. State ORE (Rectangular) N. F. SIVUSLAW Dist. HEB0

2. Corner Status 3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1898
alder post. #697

5. Investigation Notes:
Post gone
By measurement from sec. corner to secs. 16-17-8-9 south on old blazed line found a standing alder S. 66° E., 4 ft. with a witness face but all scribbling is rotted away. also found a fallen alder N. 44° W., 10 1/2 ft. with a witness face but all scribbling is rotted away.
Due to the fact these two alder are in proper bearing and measurement and the corner position is in line with the old line blazes I set a corner.

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic
Needs Verif. Monument
Re-estab. Survey
Land Status N.F.

6. Signed L. Whitmore Title Forestry aid Date 2-26-61

Remarks: Set a lead for corner 4 in diameter 4 feet long in ground scribed 1/4 S 17 on W. face and 1/4 S 16 on E. face of post.
Set a mound of stone south of corner post with a 3 foot base and 1 foot high.
new BT's
16 in. alder S. 79° W., 24 ft. scribed in bark 1/4 S 17 BT
17 in. alder N. 42 1/2° E., 11 1/2 ft. scribed in bark 1/4 S 16 BT

13. Recorded By _____ Volume _____ Page _____
(Date) (City) (County) (State)

Remarks:
THIS COR. IS LOCATED WITHIN L. Whitmore
A FUTURE ALDER SALE. TO FURTHER M. Whitmore
FOR PRESERVATION OF THE CORNER POINT I MARK ADDITIONALLY S 2° S N 66° E., 7 FT. MKD. 1/4 S 16 BT.
L. Whitmore 11-29-65