

45 R. 7W. No. 5 N. Cor. Sec. Mer. Will. State ORE. (Rectangular) N. F. Siuslaw Dist. Heb

2. Corner Status

18	17
19	20

3. Original Description Vol. Page Where Recorded

4. Description of Corners: 1879 Post #698

5. Investigation Notes: post gone
 Found old original line blazes to the south and to the east of this corner point.
 Found 30 in. fir snag N. 65° E. 86 lbs. and 18 in. cedar stump S. 86° E. 140 lbs. of which are the original recorded witness trees but all scaling is rotted away.
 Due to the fact these BT's are in their proper bearings and measurements and the original line blazes intersect at this point I set the corner at this point along the east bank of a creek for sec. 19-20 on the south boundary of sec. 17.

6. Signed: L. Whitmore Title: Forestry aide Date: 6-7-61

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey _____
 Land Status N.E. - DRW.

PERPETUATION RECORD

Argument: Let branch pipe for corner

11. Accessories new BT's
 20 in. alder S. 31° W. 21 1/2 ft. mhd. S198T
 22 in. alder S. 24° 30' E. 22 9/16 ft. mhd. S20BT

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: By M. Whitmore in presence of Bernie Sheehan Robert Long