

2. Corner Status

195210

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
Past

#700

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. Monument
Re-estab. _____ Survey _____
Status _____

5. Investigation Notes: Past zone

Found 5 in. fir snag N. 10° E, 61 1/2 ft. with all mbs. rotted off.

Found 4 3/4 in. fir stump N. 16° W, 59 1/2 ft. with all mbs. rotted off.

old original line blazes were found north and south of this corner point and these two snags are at correct bearing and distances as of the old field notes, therefore I reestablished this corner

6. Signed _____ Title _____ Date 3-28-61

PERPETUATION RECORD

Monument: Set a for limb past 7 in. x 4 in. x 24 in. high.

11. Accessories
new BT
12 in. fir N. 21° W, 47 1/2 ft. mbd. 1/4 S 19 BT.
16 in. fir S. 8° E, 19 ft. mbd. 1/4 S 20 BT.

By m. whitmore

12. Set By _____ Title _____ License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks