

1. T4S R9W No13-V Cor. SEC Mer. Will. State ORE. N.F. SILVSLAW Dist. HEBD

2. Corner Status

| | | |
|--|----|--|
| | | |
| | 27 | |
| | | |

3. Original Description Vol. Page Where Recorded #706

4. Description of Corners:
CC section corner west boundary between secs. 27-34

5. Investigation Notes:
Find a 24 X 12 X 8 in. unmarked stone. I believe this stone to be the corner monument as no other stones are in the immediate vicinity of this large flat. also it is on the north-south section line.
Find a 60 in. snag, S. 5° E., 57 ft. mbd. T4SR9W S34

6. Signed L. Whitmore Title Forestry aid Date 3-19-62

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By: _____
Field Book No. _____
Where Filed: _____

9. Evaluation
Authentic _____
Needs Verif. Monument _____
Re-estab. Survey _____
Land Status N.F.

PERPETUATION RECORD

10. Monument: 24 X 12 X 8 inch unmarked stone.

11. Accessories new BT's
16 in. alder, S. 75° E., 62 ft. mbd. S34 BT
16 in. fir, N. 54° E., 25 1/2 ft. mbd. S 27 BT

12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____
(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:
The corner is located on a brush flat about 180 ft. south of a creek.
Leonard Whitmore
Mervin Whitmore