

Index File No. <u>45</u>	CORNER RECORD (SEARCH)		Tract or Survey No. _____	Cor. No. <u>T-1</u>
T. <u>4S</u> R. <u>9W</u>	R.D. <u>HeBO</u>	County <u>TILLAMOOK</u>	#712	
Merid. <u>Will</u>	N.F. <u>SIUSLAW</u>	State <u>ORE.</u>		
CORNER DIAGRAM		DESCRIBE CORNER MONUMENT FOUND <u>GLD 1879 SET POST AND MKD:</u>		
		A 24" FIR, N. 82° E., 67 LKS.		
		A 60" FIR, S. 47° W., 20 LKS.		
PHOTO IDENTIFICATION DATA		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND		
Photo No. _____		By Record M. WHITMORE, USFS, 5-18-52 FOUND 24" SNAG,		
Filed At. _____		N. 82° E., 67 LKS. WITH MKS. 1/4 SBT.		
Object Ident. _____		A 60" SNAG, BEARS, S. 47° W., 20 LKS. WITH MRKS. ROTTED OFF.		
Ident. By _____		He MKD 2 NEW WITNESSES:		
Signature _____		A 14" ALDER, N. 57° W., 13 LKS. MKD. 1/4 S 25 BT.		
Agency _____		A 26" ALDER, N. 44° E., 67 LKS. MKD. 1/4 S 30 BT.		
PLANE COORDINATE POSITION DATA		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER		
State _____ Zone _____		1-69 THE DISTRICT ENGINEERS FOUND THIS CORNER AS		
X _____		OF WHITMORES RECORDS.		
Y _____				
Estab. By _____				
Agency _____				
Signature <u>Leonard Whitmore</u>	Title <u>Forestry Tech</u>	Division <u>Timber</u>	Headquarters <u>Hebo</u>	Date <u>1-31-69</u>
				7100-52 REV. 65 5

No additional information

Leonard Whitmore is a Deputy County Surveyor
qualified to re-witness authentic original
monuments.

[Handwritten signature]

[Handwritten text]