

CORNER RECORD (SEARCH) <small>(Ref. FSM 7151.4)</small>		Tract or Survey No. _____	Cor. No. <u>2-5</u>
No. <u>40</u>	S. R. <u>9W</u>	R.D. <u>Hebo</u>	County <u>TILLA</u>
Merid. <u>WILL.</u>	N.F. <u>SIUSLAW</u>	State <u>ORE.</u>	#714
CORNER DIAGRAM 		DESCRIBE CORNER MONUMENT FOUND <u>GL 1878 SET 14X12 X 6 STONE</u>	
PHOTO IDENTIFICATION DATA Photo No. <u>EIJ-9-195</u> Filed At: _____ Object Ident. _____ Ident. By _____ Signature _____		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND <u>FOUND 14X12 X 8 STONE WITH 3 ROCKS AROUND ITS BASE. OLD LINE BLAZES ARE FOUND TO THE EAST, NORTH AND WEST. A CREEK RUNNING NW 18 1.50 CHAINS TO THE NORTH AS IN RECORDS.</u>	
PLANE COORDINATE POSITION DATA State _____ Zone _____ X _____ Y _____ Estab. By _____ Agency _____		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER <u>I FOUND A 32" FIR, N. 16° W., 4³ FT. AND A 32" ALDER, S. 29° E., 18 1/2 FT. WITH F.S. LOCATION TAGS REFERENCED BY M. WHITMORE, USFS, 4-26-61. I BLAZE X & PAINT RED BAND AROUND ABOVE REFERENCES. SET 2X2 X 40 PITCH SLAB ALONGSIDE STONE.</u>	
Signature <u>Lemond Whitmore</u>		Title <u>Forestry tech</u>	Division <u>Hebo</u>
Date <u>5-5-69</u>		Headquarters <u>Hebo</u>	Date <u>7100-52 (3/68)</u>

CORNER RECORD (PERPETUATION)			
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT			
ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE			
Work Done By _____	Title _____	Date _____	State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes _____ No _____	Filed At: _____	Date _____	
REMARKS			
<u>THE CORNER IS LOCATED IN A BOTTOM BETWEEN TWO SMALL GULLEYS THAT COME TOGETHER 100 FT. TO THE SOUTH. TWIN FIRS STAND 5 FT. TO THE SOUTH.</u> <u>NOTE: Lemond Whitmore is a Deputy County Surveyor, qualified to set witnesses & re-monument. POSITIVE FOUND OLD CORNERS. [Signature]</u>			
Index File No. <u>T</u>	<u>R</u>	<u>M</u>	Tract or Surv. No. _____
			Cor. _____