

1. T. S. R. 70 No. J. I. Cor. SEC. Mer. WILL State ORE. (Rectangular) N.F. SIO SLAW Dist. HEBO

2. Corner Status 4. S. 11 - 18 5. 10

12	7
⊗	
13	18

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1979 **#730**
POST

5. Investigation Notes:
 Find old post, with squared top, lying under
 mass upon the ground.
 Find two pine trees nearby with cross notches on
 each signifying the position of the corner, thereby
 locating the former post.
 Counting the rings from the outside of the pines to
 the notches signify the notches were made 50 years
 ago.
 After exhausting all bearing tree possibilities I am
 convinced all original BTs are gone.

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filled _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. _____ Survey _____
 Land Status PRIV. - N.F.

6. Signed L. WHITMARE Title FORESTER AID Date 10-4-60

10. Monument: **PERPETUATION RECORD**
Set a dead pine limb at base of old post for true corner.

11. Accessories
put a location poster on 6 in. pine S. 34° W, 12 ft.
" " " " 8 in. pine N. 1° E., 6 1/2 ft

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:
corner is located on sandy pine flat.