

**CORNER RECORD (SEARCH)** (Ref. FSM 7151.4) Tract or Survey No. \_\_\_\_\_ Cor. No. **731**

**J-15**  
 R. 10 W. D. **HEBO** County **TILLA.**  
 W. M. N. F. **STANSLAW** State **ORE.**

**DIAGRAM**  
 CORNER MONUMENT FOUND  
 GLO 1879 SET FIR POST & MARKED:  
 40' SNAG, S 16° E, 71 LKS.  
 14" SNAG, N 56° E, 66 LKS.

**DIAGRAM**  
 CORNER MONUMENT FOUND  
 M. WHITMORE, 1955 SET 3/4" IRON PIPE 2' HIGH.  
 HE FOUND 54" SNAG, S. 16° E, 48 FT. SLOPE DISTANCE.  
 FACING IS SHOWING BUT SCRIBING IS WEATHERED AWAY. HE REMARKED THIS TREE "1/4 S 15 BT."  
 A ROTTED FIR STUMP, N. 56° E, 43' SLOPE DIST. MARKS ROTTED AWAY.

**IDENTIFICATION DATA**  
 Date No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Entered By **WCE22081E2**  
 Signature \_\_\_\_\_

**COORDINATE POSITION**  
 Date \_\_\_\_\_  
 Zone \_\_\_\_\_  
 Description \_\_\_\_\_  
 Entered By \_\_\_\_\_  
 Agency \_\_\_\_\_

**DESCRIPTION**  
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
 M. WHITMORE SCRIBED ONE NEW BT.  
 30" FIR, 6 PRONGED TOP, N. 42° E, 36 FT. SLOPE DIST. SCRIBED "1/4 S 10 BT."  
 I FOUND THE PIPE AND BT'S IN GOOD CONDITION. REMEASURE TO SIDE CENTER AND HORIZONTAL DISTANCES. 36 FT. TO N. E. BT. 47 FT. TO S. E. BT. **Leonard Whitmore** 4-15-76

**CORNER RECORD (RE-EVALUATION)**

**MONUMENT** DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

**ACCESSORIES** DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At \_\_\_\_\_ Date \_\_\_\_\_

**REMARKS**  
 CORNER IS ON GENTLE S.W. SLOPE IN HEAVY STAND OF SALAL.  
 T. 4S R. 10W 1/4 Cor. 10/15