

MONUMENT; DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#733


ACCESSORIES; DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING ETC.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

FOUND THE CORNER PIPE & BT'S IN PROPER POSITION.
CORNER IS ON EAST EDGE OF SACRIFICATION.
L. Whitmore, 1-13-76

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract No. J-25 Cor. No. J-25
 Surveyor UPDATED
 No. J-25 R. 10W R.D. Hebo County TILLA.
 Sec. 4S N.F. SLUSLAW State ORE. - 1976
 World. Will

CORNER DIAGRAM


DESCRIBE CORNER MONUMENT FOUND
 GLO 1879 SET POST & MKD;
 20" SNA9, N. 33° W, 95 LKS.
 28" SNA9, N. 43° E, 250 LKS.
 30" SNA9, S. 41° W, 395 LKS.
 14" SNA9, S. 50° E, 196 LKS.
 M. WHITMORE, USFS, 4-17-53 SET A
 POST & MKD. 2 WITNESSES:
 26" ALDER, N. 50° W, 42 FT. SLOPE DIST.
 MKD. T4SR10WS12BT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 A 18" ALDER, S. 46° W, 4 1/2 FT. SLOPE DIST. MKD. T4SR10WS12BT
 FOUND 2 X 3 X 20 WOOD POST MKD. S13 ON S. SIDE WITH
 3/4" GALV. PIPE ALONG SIDE.

PHOTO IDENTIFICATION DATA
 Photo No. EIT-10-35
 Found At. _____
 Object Ident. _____
 Ident. By WCE2208103
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 FOUND 58" SNA9, N. 43° E, 250 LKS. WITH MKS. T4SR9WS7BT.
 THE ORIG. NW, SW, & SE BT'S ARE ENTIRELY GONE.
 FOUND WHITMORES. RE-WITNESSED TREES AS IN HIS
 RECORDS.
 PAINT RED BAND & PUT BT SIGNS ON WITNESSES.
 THE CC COR. TO SECS. 7-18 IS 87 LKS. NORTH

PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____
 Y _____

Estab. By WCE2208103 Signature Leonard Whitmore Date 15-13-69