

Index		CORNER RECORD (SEARCH)		Tract or Survey No.		Cor. No. <i>J-25</i>	
File No.		(Ref. FSM 7151.4)					
T. <i>4S</i>	R. <i>10W</i>	R.D. <i>HEBO</i>	County	<i>TILLA</i>	# <i>735</i>		
Merid. <i>Will</i>	N.F. <i>SIUSLAW</i>	State	<i>ORE.</i>				
CORNER DIAGRAM		DESCRIBE CORNER MONUMENT FOUND <i>GLO 1879 SET POST & MKD;</i>					
		<i>20" SNA9, N. 33° W, 95 LKS.</i> <i>28" SNA9, N. 43° E, 250 LKS.</i> <i>30" SNA9, S. 41° W, 395 LKS.</i> <i>14" SNA9, S. 50° E, 196 LKS.</i>					
		<i>M. WHITMORE, USFS, 4-17-53 SET A POST & MKD. 2 WITNESSES;</i> <i>26" ALDER, N. 50° W, 42 FT. SLOPE DIST. MKD. T43R10W S12BT.</i>					
PHOTO IDENTIFICATION DATA		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND					
Photo No. <i>EIT-10-35</i>		<i>A 18" ALDER, S. 46° W, 4 1/2 FT. SLOPE DIST. MKD. T43R10W S12BT</i>					
Filed At. _____		<i>FOUND 2 X 3 X 20 WOOD POST MKD. S13 ON S. SIDE WITH</i>					
Object Ident. _____		<i>3/4" GALV. PIPE ALONG SIDE.</i>					
Ident. By _____		<i>FOUND 58" SNA9, N. 43° E, 250 LKS. WITH MKS. T43R9W S7BT.</i>					
Signature _____		<i>THE ORIG. NW, SW, & SE BT'S ARE ENTIRELY GONE.</i>					
PLANE COORDINATE POSITION DATA		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER					
State _____ Zone _____		<i>FOUND WHITMORES. RE-WITNESSED TREES AS IN HIS</i>					
X _____		<i>RECORDS.</i>					
Y _____		<i>PAINT RED BAND & PUT BT SIGNS ON WITNESSES.</i>					
Estab. By _____		<i>THE CC COR. TO SECS. 7-18 IS 87 LKS. NORTH</i>					
Agency _____		Signature		Title	Division	Headquarters	Date
		<i>Leonard Whitmore</i>		<i>Forester Tech</i>	<i>Timber</i>	<i>Hebo</i>	<i>5-13-69</i>
							<i>7100-52 (3/68)</i>

No additional information

*LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR
 EMPOWERED TO RE-WITNESS AUTHENTIC ORIGINAL
 MONUMENTS
 3/10/80 *John Carter County Surveyor**