

| CORNER RECORD (SEARCH) | | Tract or Survey No. | Cor. No. |
|---|--|--|-------------|
| No. <u>N-21</u> | | | |
| <u>5</u> R. LOW RD. <u>HEBO</u> | | County <u>TILLA</u> | <u>#736</u> |
| Merid. <u>W.M.</u> <u>N.F. SIOUSLAW</u> | | State <u>ORE.</u> | |
| CORNER DIAGRAM | | DESCRIBE CORNER MONUMENT FOUND | |
| | | <u>GLO 1879 SET POST & MKD;</u> <u>24" FIR, N. 80° E, 48 LKS. BREAK 6 CHAINS EAST.</u> <u>20" FIR, N. 60° W, 100 LKS.</u> <u>38" FIR, S. 32° W, 34 LKS.</u> <u>24" FIR, S. 39° E, 136 LKS.</u> | |
| | | DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND | |
| | | <u>FOUND 3/4" GRAY PIPE.</u> <u>FOUND DECAYED FIR STUMP, N. 80° E, 48 LKS.</u> <u>FOUND BADLY DECAYED FIR STUMP, N. 60° W, 100 LKS.</u> <u>FOUND DECAYED FIR STUMP, S. 32° W, 34 LKS.</u> <u>FOUND 50" SNAG, S. 39° E, 136 LKS. WITH FACE WEATHERED AWAY, WITH A OLD RUSTED LOCATION TIN MARKED;</u> | |
| PHOTO IDENTIFICATION DATA | | DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER | |
| Photo No. _____ Filed At. _____ Object Ident. _____ Ident. By _____ Signature _____ | | <u>OLD BEARING TREE;</u> <u>FOUND A CREEK 6 CHAINS EAST AS IN ORIG. NOTES.</u> <u>IT IS MY OPINION SCRIBING WAS SEEN ON THE S.E. BT WHEN THE LOCATION SIGN WAS ATTACHED.</u> | |
| PLANE COORDINATE POSITION DATA | | Signature _____ Date _____ | |
| State _____ Zone _____ | | <u>Edward W. Lutzmore</u> <u>4/14/76</u> | |
| X _____ | | | |
| Y _____ | | | |
| Established By _____ | | | |

| CORNER RECORD (PERPETUATION) | |
|---|--|
| MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT | |
| | |
| ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE | |
| | |
| Work Done By _____ | Title _____ |
| Date _____ | State Registration No. or Agency _____ |
| Certified Cor. Record Prepared? Yes _____ No _____ | Filed At _____ Date _____ |
| REMARKS | |
| <u>ATTACH LOCATION SIGN ON A ALDER, S. 43° W, 10 FT.</u> | |