

TILLAMOOK COUNTY REWITNESS #743
 1/4 COR. 12 T 4S R 10 W., WM.


HISTORICAL: GLO--4510--Page 19
 Book 1 Page 57 Book 4 Page 17
 WEA MAP A-714 MAP A-765 by John L. Carllich
 J.L. Carllich MAP A-1329

CONDITION	FOUND:
GOOD	1" Iron Pipe with Tack
1971	Fd 1 1/2" IRON PIPE with Brass Cap
	Fd TWO B.T.S. MADE IN 1969 - BOTH O.K.

COMMENTS:

REWITNESS

1 SET 1 1/2" Iron Pipe with Brass Cap With CEMENT & TILE 1971



* 96 " Hat Section	S. South 15 feet
NEW ACCESSORY:	
* 10" Maple	S 29° W 7.09
* 32" Spruce	N 85° W 28.98
* 10" MAPLE N 22° E	28.24 feet 11-19-71

COMMENTS: With permission of the County Surveyor, I replaced the existing 1" Iron Pipe. Highway 101 bears South \pm 60 feet to apparent center line of Highway 101. A small shed bears due north \pm 20 feet from $\frac{1}{4}$ corner. Monument is located above highway cut.

IN THE PRESENCE OF: Gale Arthur | Gale Arthur
 George Urrey | Roger Knippel

DATE: 1969 & 1971 PHOTO #: SEC
 * - County corner tag affixed. TILLAMOOK COUNTY TITLE GWU '71