


TILLAMOOK COUNTY REWITNESS #745



REV. 10/10/71
 1/4 COR. SEC. 12 T. 45 R. 10 W., WM.
 SEE DEC.

HISTORICAL: MAP B-526 Bk. 53 Page 338

60 Bearing Trees 36" fir N8°E 165 Lbs
 1879 15" fir S18°W 222 Lbs


1966 - 1/4 corner 1/3 - found by L.E. FULTZ

CONDITION	FOUND:
Good	Iron Truck AXLE
Tree is standing	30" Alder BT Scribing is barely visible
Tree is standing	Dead 10" Alder BT - which had been faced and is starting to rot

COMMENTS: 11-19-71 Fd Truck AXLE - REPLACED IT WITH BRASS CAP
 Fd Bearing trees MADE IN 1969 - All in good condition

REWITNESS

"1971 NOVEMBER" SET 2" IRON PIPE WITH BRASS CAP IN CEMENT & TILE SOUTH 12 feet



6" Hat Section S. #2
 NEW ACCESSORY: With permission from the Co. S. -- I made
 two new bearing trees as follows:
 South 1/4 Sec 12 - BT Triple Alder with 30" base North 41 26
 North 1/4 Sec 13 - BT 14" Alder S82°E13 27

COMMENTS: Center line of Mount Hebo Road is ± 75 feet Eastern of 1/4 Corner

IN THE PRESENCE OF: George Urrey / Gale Arthur
 Roger Knippel
 COB: Gale Arthur

DATE: 1969 & 1971 PHOTO: REC
 TILLAMOOK COUNTY DEPUTY CLERK TITLE: G.W. '11