

Index File No. N-13	CORNER RECORD (SEARCH)		Tract or Survey No.	Cor. No.				
T4S R10W	R.D. Hebo	County Tillamook	#753					
Merid. Willamette	N.F. Siuslaw	State Oregon						
CORNER DIAGRAM T4S R10W	DESCRIBE CORNER MONUMENT FOUND							
<table border="1"> <tr><td>16</td><td>15</td></tr> <tr><td>21</td><td>22</td></tr> </table>	16	15	21	22	Found original post that M. Whitmore found in 1958 - Also 3/4" pipe set at same time The post is in poor condition.			
16	15							
21	22							
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND							
	36" stump remains brs. S23W 12.5' 40" snag 6 ft high brs. N65W 73.0' (orig) no scribing visible							
PHOTO IDENTIFICATION DATA	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER							
Photo No.	Take a right at Cloverdale - go across bridge - TAKE							
Filed At	first road for road heading north across wooded fi.							
Object Ident.	go up cat road staying left till you reach old FIELD							
Ident. By	landing - go up road to right to corner.							
Signature								
PLANE COORDINATE POSITION DATA								
State	Zone							
X								
Signature	Title	Headquarters	Date	NO				
<i>T.O. McCullough</i>	<i>Surveyor</i>							

OBJECT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	
at 2" x 30" iron pipe with brass cap mkd T4S R10W	16 15 21 22 1970 650
ACCESSORIES: DESCRIBE NEW BY: WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE	
spruce brs. 941E 37.5 ft -- scribed T4S R10W S22 BT -- with tag	
placed post and pipe alongside corner	
Set 2 fence posts with signs + 5 ft north facing west - 5 ft east facing south	
Work Done By <i>T.O. McCullough</i>	Surveyor Date <i>4/21/70</i> State Registration No. or Agency
Certified Cor. Record Prepared? Yes No	Filed At Date
REMARKS	
witnesses to the above corner: Dick Rust Bill O'Key	