

#755

Survey No. _____ No. _____

T15 R10W R.D. Hebo County Tillamook
 Merid. Willamett N.F. Siuslaw State Oregon

CORNER DIAGRAM DESCRIBE CORNER MONUMENT FOUND

T15 R10W
 16
 21

Found 1/2" pipe set by M. Whitmore in 1951

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

36" fir snag brs. S20W 28.4 ft - no marks
 72" snag brs. N35E 15.2 ft - faint scribe marks
 Above are original BTs
 28" fir brs. S33W 13.5 ft - scribed - with tag
 20" fir brs. N12E 34.9 ft - scribed - with tag

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take a right at Cloverdale - go across bridge - take first road to left to woods - then go 3/4 mile to road heading north across wooded field - go up cat road - stay left until you cross creek, then go to north up small ridge to the E1/10 - then west for 20 ch. to 1/2 corner - corner is on ridge running N-S

PLANE COORDINATE POSITION

State _____ Zone _____
 X _____
 Y _____

Signature _____ Title _____
 Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2"x30" iron pipe with brass cap mkd T15 R10W
 16
 21
 1970
 650

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set pipe alongside corner.
 Set fence post with signs ± 5 ft. east facing south

Done By J. O. McCullough Title Surveyor Date 4/21/70 State Registration No. ORLS 650
 or Agency _____

Certified for Record Prepared? Yes No Filed At _____ Date _____

REMARKS

witnesses to the above corner: Dick Rust
 Bill O'Key