

T. 45 R10W No. V21 Cor. SEC Mer. Will State <sup>(Rectangular)</sup> ORG. N. F. SIUSLAW Dist. Hebo

2. Corner Status

	25	

26  
35 36

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: #773

5. Investigation Notes:  
 FOUND 3/4 IN. GALV. PIPE 26 IN. ABOVE GROUND.  
 FOUND 5 1/2 IN. SAW-OFF FIR STUMP, N. 26° E, 68 LKS. WITH A VISIBLE T  
 FOUND 5 1/2 IN., FIR SNAG, S. 16° W, 43 LKS. WITH VISIBLE MARKS 5 T 4  
 THE N.W. BT IS IN ITS PROPER BEARING AND DISTANCE BUT ALL MARKS ARE ROTTED AWAY.  
 THE S.E. BT IS ENTIRELY GONE.

6. Signed L. WHITMORE Title FORESTRY TECH Date 5-27-63

7. Photo Identification  
 Photo No. \_\_\_\_\_  
 Ident. By: \_\_\_\_\_

8. Plane Coordinate Position Data  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Field Book No. \_\_\_\_\_  
 Where Filed \_\_\_\_\_

9. Evaluation  
 Authentic   
 Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_  
 Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
 Land Status PRIV. - PD

Monuments

Note Leonard Whitmore is a DEPUTY COUNTY SURVEYOR qualified to REWITNESS & REMONUMENT POSITIVE OLD

11. Accessories MONUMENT found  
 off center of s slash

12. Set By \_\_\_\_\_ Title \_\_\_\_\_  
 License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_  
 (Agency) \_\_\_\_\_  
 (Date) \_\_\_\_\_ (City) \_\_\_\_\_ (County) \_\_\_\_\_

14. Remarks: New BTs  
 24 IN. HEM., N. 24° E, 18 LKS. MKD. T4S R10W S 25 BT  
 22 IN. HEM., N. 63° W, 21 LKS. MKD. T4S R10W S 26 BT  
 26 IN. HEM., S. 11° W, 42 LKS. MKD. T4S R10W S 35 BT  
 6 IN. SPRUCE, S. 18° E, 50 LKS. MKD. X BT  
 CORNER IS AN WEST SLOPE. L. WHITMORE