


CORNER RECORD (SEARCH)		Tract or Survey No.	Cor. No.
18 No. <u>45 R. Low</u>	R.D. <u>Hebo</u>	County <u>TILLA</u>	<u>#805</u>
Merid. <u>Will.</u>	N.F. <u>KUSLAW</u>	State <u>ORE.</u>	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND		
	<p>6 L 1878 SET POST & MARKED; 56" FIR, S. 75° E., 10 LKS. 48" FIR, N. 55° W. (NOT 35°) 73 LKS.</p>		
PHOTO IDENTIFICATION DATA	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND		
Photo No. _____	<p>BY RECORD M. WHITMORE, USFS, 4-30-48 FOUND THE ORIGINAL POST WITH SCRIBE MARKS "45" ON N. SIDE FROM WHICH A 48" SNAG, S. 55° E., 73 LKS. HAD VISIBLE SCRIBE MARKS.</p>		
Field At. _____	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER		
Object Ident. _____	<p>AT A LATER DATE 4-23-64 HE SET 1" GALV. PIPE AT CORNER POINT & WIRE OLD POST TO PIPE & MARKED</p>		
Set. By _____	<p>28" FIR, S. 77° W., 35 LKS. MKD. 1/4 S 3 BT. 12" FIR, N. 56 1/2° E., 40 LKS. MKD. 1/4 S 34 BT.</p>		
LINE COORDINATE POSITION DATA	Date <u>7/10-22 19/68</u>		
State _____ Zone _____	Headquarters _____		
Estab. By _____	Agency _____		

PERPETUATION RECORD	
10. Monument:	The orig. post MKD. 1/4 S is wired to an iron pipe.
11. Accessories	Note: Leonard Whitmore is a Deputy County Surveyor qualified to Re-witness & Re-monument Positive OLD MONUMENTS found. <u>Richard C. Smith</u> 6/70
12. Set By _____ Title _____	13. Recorded By _____ Volume _____ Page _____
License _____ Agency _____ Date _____	(Date) _____ (City) _____ (County) _____ (State) _____
14. Remarks: New BT ^s MKD. By M. WHITMORE AND B. SHEEHAN 4-23-64	
28 IN. FIR, S. 77° W., 35 LKS. MKD. 1/4 S 3 BT.	
12 IN. FIR, N. 56 1/2° E., 40 LKS. MKD. 1/4 S 34 BT.	
THIS COR. IS ON S. EDGE OF OLD LOGGING AREA.	