

55 R. 9W. S.D. HERO Survey No. \_\_\_\_\_  
 County TILLAMOOK # 819  
 Merid. 411 V.F. SLOSLAW State  
 CORNER DESIGN DESCRIBE CORNER MONUMENT FOUND  
 CAUDLE 1880 SET 16X10X4 STONE.  
 6 LO  
 4  
 9  
 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
 I FOUND A 16X10X4 STONE MARKED  $\frac{1}{4}$  ON E. AND W. SIDES.  
 PHOTO IDENTIFICATION DATA  
 Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Subject Ident. \_\_\_\_\_  
 Taken By. \_\_\_\_\_  
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
 THIS CORNER SETS ON A SPUR SLOPING TO THE SOUTH  
 NAME COORDINATE POSITION DATA  
 Date \_\_\_\_\_ Zone \_\_\_\_\_  
 Signature \_\_\_\_\_ Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_  
 Leonard Whitmore Forestry Tech Timber Mebo 2-13-68 7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

I SET 1" PIPE ALONG SIDE EAST SIDE OF STONE, (ORIG).  
 BRASS CAPPED BY BLM 1972

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I MARKED 2 BT'S:  
 A 24" FIR, S. 63° W, 4 FT. MKD.  $\frac{1}{4}$  S 9 C SBT.  
 A 24" FIR, N. 79° E, 20 FT. MKD.  $\frac{1}{4}$  S 4 C SBT.

Leonard Whitmore, Tillamook Co. Dep. Surveyor Witness: Fred Johnson

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_  
 Certified Cor Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS  
 LEONARD WHITMORE  
 BRASS CAPPED BY BLM 1972